


Redkite Systems AMS Defect Management



AMS Defect Management Module

Your assets are valuable and when they need repairing you want to keep track of where they are in the repair process and be kept informed of progress.

The Redkite AMS Defect Management Module tracks progress and keeps relevant people informed via email or SMS.

EQ Code	Description	Defect	Location	Barcode No.	Status	Date	Required Date	Completed Date	Priority	Reference
OH03100001	*BRANCH - FB5X & P/UP TUBE	FRAYED CABLE	01 - COVENTRY	00020542	OPEN	02/05/2014			●	DEF49
OA00200001	BA - CYLINDER 1800LTS	DEFECTED	SOME TOWN	123456789	IN REPAIR	02/05/2014			●	DEF50
OA00200001	BA - CYLINDER 1800LTS	CRACKED WINDSCREEN	SOME TOWN	123456789	CONTRACTOR ASSIGNED	02/05/2014			●	DEF51
OL00406003	*LADDER - ROOF	DEFECTED	04 - NEWCASTLE	00020509	OPEN	25/03/2014			●	DEF38
OA00200001	BA - CYLINDER 1800LTS	DEFECTED	SOME TOWN	123456789	CONTRACTOR ASSIGNED	08/01/2014			●	DEF34
OA00200001	BA - CYLINDER 1800LTS	DENT IN BODY	SOME TOWN	123456789	AWAY FOR REPAIR	08/01/2014			●	DEF36

- ✓ Integrates seamlessly with the Redkite AMS Core Module allowing defect actions to be created when an asset fails a test or inspection
- ✓ Responsible personnel receive Email /SMS notifications of new defects, updated defect status and completed defects with direct link back to the defect record
- ✓ Tracks progress through the repair process
- ✓ Tracks actual versus estimated costs and invoice detail
- ✓ An extensive range of management reports provide a wealth of information from a comprehensive query screen
- ✓ Colour coded defect priorities for ease of use
- ✓ Current status showing Total Defects Closed, Total Defects Open, Total Defects Pending, Total Defects Replacements needed, etc. always shows on Defects Search screen

Defect Details			
Ref: DEF33	Equipment code: OA00200001	Barcode No.: 123456789	Serial No.: ALT1110
Defect date: 07/1/2014	Defect type: EQUIPMENT	Status: OPEN	Priority: Green
Completed date:	Defect description: DEFECTED	Recorded By: 12345 MARTIN	Date: 07/01/2014
Repairer type: Internal	Contractor 1	Contact name: John Smith	Telephone No.:
Estimated cost: 0	Actual cost: 0	Cost allocation:	Invoice No.:
Assigned external repairer: Contractor 1	Email sent to external contractor: Contractor 1	Recorded By: 12345 MARTIN	Date: 08/05/2014 09:47:47

